Dec. 1973	g gudget Buregu No. 42€R1424					
UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE NM-33 01 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2					
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME					
	_ N/A %					
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME N/A					
(Do not use this form for proposals to drill or to deepen or plug back to a differenceservoir. Use Form 9–331–C for such proposals.)						
1 all V gas —	MAGNUM SERS					
1. oil X gas other	9. WELL NO.					
2. NAME OF OPERATOR	# 1 2000 2000					
LOBO PRODUCTION	10. FIELD OR WILDCAT NAME Escrito Gallup					
3. ADDRESS OF OPERATOR P.O. Box 2364, Farmington, New Mex. 8749	9 11. SEC., T., R., M., OR BLK. AND SURVEY OR					
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 1	Sec. 3 28, T 24N, R27W					
below.) AT SURFACE: 1750' FSL, 800' FEL	12. COUNTY OR PARISH 13. STATE					
AT TOP PROD. INTERVAL:	Rio Arriba New Mex.					
AT TOTAL DEPTH:	14. API NO.					
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	計					
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)					
	2 8 4 7 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:						
TEST WATER SHUT-OFF	ညည်းသောက် သို့ အမြို့အက် ညီမြို့သည်					
FRACTURE TREAT	a HIVE DOBLA STATE					
SHOOT OR ACIDIZE U PREPAIR WELL U PR	(NOTE: Report results of multiple completion or zone					
	EV a g 198chenge on Form 9-330.)					
MULTIPLE COMPLETE	HELD OF THE STATE					
CHANGE ZONES	FLAGU STATE AND STATE OF STATE					
ABANDON* Remedial Work MADANO	ON THE CHARLES WASHINGTON TO SERVE STORY					
(other)						
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly s	tate all pertinent details, and give pertinent dates					
including estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones perting	s directionally officed. Rive subsuitace locality is all					
measured and true vertical depths for all markers and zones pertin	# 한 사용 지 수 하고 기를					
	ကြောင်းကြောင့် မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက်သော မြောက					
May 19T.D. well 6114'. Circulated 2 he	ours. Ran DIL, CND Logs.					
•						
	\tilde{c}_{i}					

Ran 152 jts, 4 1/2" 10.5# casing. Land 6410'- Circulated 30 minutes. 5 BB1. mud flush, 420 sks C/H and 2% gel. Circulated and WOC 3 hours

Second Stage- 5 BBL. mud flush, 1150 sks C/B and 2% econo fill.

Tailed w/ 125 sks. C/H and 2% gel. Circulated 5.6 BBL.cement
to surface, plug down 4:30pm.

				1			
Subsurface Safety Valve: Manu. and Type			s	et @	<u> </u>		_ Ft.
18. I hereby certify that the foregoing is t	rue and correct		୍ଷ୍ଟ ପ୍ର ପ୍ରକ୍ର		ં દુધુ_,		
GNED TO THE TOTAL OF THE TOTAL	Operator Operator	DATE	May	<u>72∌,</u> 53	1984	변원 <u>설명</u> 취실물	
R C District	(This space for Federal or State office use)		1 3 3	1 00	ि है। हैं क	1	
APPROVED BY	TITLE	DATE	- 1 H	~ <u>~</u>	1 2	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	
CONDITIONS OF APPROVAL, IF ANY:			₹ <u>#</u>	140p	ି ଅଞ୍ଚଳ ଓଡ଼ିଆ	et ne oitsi	· •
DECEIVEM		ACC	EP III	FO FO	RE RE	gort	
	*See Instructions on Reverse Side		YAM	2.9	1982	.1	
MAY 2 9 1984			*****	N 0	100	'	

OIL CON. DIV. DIST. 3

NMOCL

FAKIMINGTON RESCURSE AKEA BY SAM