
MERRION OIL & GAS CORPORATION

Canyon Largo Unit 348 Sec. 6, T24N, R6W Rio Arriba Co., New Mexico

SLOPE TESTS

Depth	Hole Deviation
225	1
728	3/4
1228	1/2
1537	3/4
1680	. 3/4
2186	3/4
2805	3/4
3322	3/4
3838	1-1/4
4330	1
4710	1
4840	1



State of New Mexico County of San Juan)) ss)	• .
I, Steve S. Dunn the above and forego to the best of my in	ing dep	, being first duly sworn, depose and state that th and hole deviation figures are true and correct on and belief.
Subscribed and sworn	before	me this 4th day of April, 1985

My Commission Expires October 28, 1985