

RECEIVED

SEP 13 1988

OIL CON. DIR.
DIST. 3

ok
(E)

TABULATION OF DEVIATION TESTS

AMOCO PRODUCTION COMPANY

DEPTH	DEVIATION	Direction
70'	3/4°	
192'	1°	
272'	1°	
310'	3/4°	
456'	1 1/2°	S 35 E
573'	2 1/4°	S 37 E
728'	2 1/2°	S 39 E
911'	2 3/4°	S 40 E
1140'	3°	S 43 E
1293'	3 1/4°	S 45 E
1431'	3 1/2°	S 51 E
1593'	4°	S 53 E
1750'	4 1/2°	S 64 E
2029'	6°	S 55 E
2345'	7 1/2°	S 48 E
2656'	10°	S 44 E
2687'	10°	S 44 E
542E	6 1/2°	593E
533E	7 1/2°	587E
552E	9°	581E
548E	9 3/4°	574E
548E	10 1/2°	568E
550E	11°	562E
548E	11 1/2°	559E
542E	11 1/4°	549E
546E	11°	543E
550E	11°	537E
552E	11 1/4°	531E
		524E

<u>Depth</u>	<u>Deviation</u>	<u>Direction</u>
3125'	12 $\frac{3}{4}$ °	S 39 E
3277'	13 $\frac{3}{4}$ °	S 38 E
3434'	13°	S 36 E
3545'	11 $\frac{3}{4}$ °	S 44 E
3638'	11 $\frac{3}{4}$ °	S 43 E
3740'	11 $\frac{1}{4}$ °	S 44 E
3824'	10°	S 40 E
3889'	10°	S 40 E
4010'	11°	S 37 E
4105'	12°	S 38 E
4126'	12°	S 38 E
4191'	11°	S 40 E
4252'	11°	S 45 E
4314'	10 $\frac{1}{2}$ °	S 42 E
4377'	10°	S 45 E
4439'	9 $\frac{1}{2}$ °	S 45 E
4502'	9 $\frac{1}{2}$ °	S 42 E
4525'	8°	S 44 E
4565'	9°	S 43 E
4687'	8°	S 46 E
4749'	7°	S 46 E
4812'	7°	S 43 E
4870'	8°	S 46 E
4932'	9°	S 46 E
4983'	9 $\frac{1}{2}$ °	S 46 E
5000'	7 $\frac{3}{4}$ °	S 45 E
5062'	7 $\frac{3}{4}$ °	S 45 E
5125'	8 $\frac{1}{2}$ °	S 45 E
5184'	9 $\frac{1}{2}$ °	S 44 E