



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 172001  
Unit 3001

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 24 is located 100 ft. from N line and 100 ft. from E line of sec. 4  
14/4 100 100 100  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
100 100 100  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 100 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well has been plugged and abandoned in the following manner:

1. Perforations from 5317' to 5403', plugged w/28 oz.
2. 3 1/2" casing found free to 5403' and same recovered.
3. Plugged 38 oz. plug across slot from 5403' to 5407'.
4. Plugged 70 oz. plug from 5407' to 5411'.
5. Drilling c. 1/2 A. water w/10 oz. surface plug.

RECEIVED

JUN 14 1963



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Jeffrey Production Company

Address 201 Westside Dallas Tex.

Dallas 1, Texas

By

Title