


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **State Fe**
Lease No. **078302-1**
Unit **1**



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	X
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

2/3, 1959

Federal 7-7 #6

Well No. _____ is located **1900** ft. from **[N]** line and **660** ft. from **[E]** line of sec. **7**

SE, SW, Sec 7 **24N** **7W** **R4P1**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Monte Lower Gallup **San Juan** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6818** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The well was spudded at 4:00 PM 7/29/59. 8 5/8" casing was set at 330' and cemented to surface with 200 sac neat cement. After 24 hrs. the pipe was tested O.K. with 500 lbs. water press. At the end of the month the well was drilling at 1304' in shale.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Standard Oil Company of Texas**

Address **Box 1581**

Marion, New Mexico

By **W. L. Lantry**

Title **Field Foreman**