

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santo Fe

Lease No. NM 014580

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<u>Plug Back & Set Casing</u>	<u>x</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Dec 26 1959, 19__

Royal-Ake (

Well No. # 3 is located 850 ft. from N line and 1980 ft. from W line of sec. 10

NW 10
(1/4 Sec. and Sec. No.)

24N 8W
(Twp.) (Range)

NMPM
(Meridian)

undesignated (Paquenoche)
(Field)

San Juan
(County or Subdivision)


N Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft. GL 7063.6 DF 7075

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TD 6937 - Dakota looked questionable - Desire to plug back to 5926' and run 5 1/2" 17# N80 Casing to top of Gallup 5682' and cement 5 1/2" with 100 sacks, completing Gallup in open hole.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Royal Development Co

Address Box 1299 Albuquerque NM

By [Signature]

Title Agent