Form 9-331 (May 1963)

1.

2.

UNITED STATES DEPARTMENT OF THE INTERIOR SUBMIT IN TRIPLICATE* (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R142-5. LEASE DESIGNATION AND SERIAL NO.

٠.				,•				/
	SE	07	8875					L.
6.	SF_	IAN,	ALLOY	TEE	OR	TRIBE	N	ME

7 UNIT AGREEMENT NAME

GEOLOGICAL SURVEY						
SUNDRY N	OTICES	AND	REPORTS	ON	WELLS	

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT--" for such proposals.)

OIL GAS WELL OTHER NAME OF OPERATOR	Canyon Largo Unit 8. FARM OR LEASE NAME
El Paso Natural Gas Company	Canyon Largo Unit

9. WELL NO. ADDRESS OF OPERATOR 48 10. FIELD AND POOL, OR WILDCAT

P.O. Box 990 Farmington, New Mexico
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface At surface

Ballard P.C.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA N.M.P.M.

15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO. 6777' DF

990' N, 990' W

Sec. 33, T 25 N R 6 W

New Mexico Rio Arriba

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL

REPAIRING WELL ALTERING CASING ABANDONMENT*

(Other) Tubing Replacement
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

5-12-73 Pulled 83 its. of 2-3/8" tbg. Appears in good conditions. Ran 81 jt. 1-1/4" 2.4# 10rd. NU IJ Vinson V-55 tbg. Tagged btm. @2639' DF (2625.35') Landed @ 263! 35'. RD & move to Canyon Largo Unit #46. Btm. 10' perf'd w/2-1/4" holes/ft. &" piston stop" welded above top perf. Off report.



JUL 23 1973

II. S. GEOLOGICAL SUKVEY 0.010.

18. I hereby certify	that the for	egoing is true and correct			
signed	el-on f	egoing is true and correct	TITLE .	Production Engineer	DATEJuly 11, 1973
(This space for	Federal or S	tate office use)			
APPROVED BY CONDITIONS O	F APPROVA	AL, IF ANY:	TITLE .		DATE