

APPROVED

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

JUL 30 1956

JERRY W. LO

ACTING

DISTRICT ENGINEER

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

Land Office San Jose, Pa.

Lease No. 000375-A

Unit Shute

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 19, 1956

Well No. 2-4 is located 1440 ft. from N line and 1490 ft. from E line of sec. 6

Section 6 25N 7W NMZN

($\frac{1}{4}$ Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Large Canyon Ext. Rio Arriba New Mexico

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 7025 ft.**DETAILS OF WORK**

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-12-56. Total Depth 2925'.

Run 90 joints 5 1/2", 15.5#, J-55 casing (2916') set at 2925' with 75 sacks regular cement, 75 sacks Formix, 4% Gel, 1/2# Floccul/sk.

Hold 1000# for 30 minutes.

Top of cement by temperature survey at 1800'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farina, Tex., New Mexico

By Geo Boyd

Title Petroleum Engineer