

APPROVED

JUN 1

Budget Bureau 42-R358.2
Approval expires 12-31-55

(Orig. 564) J. W. L.

ACTING DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa FeLease No. 080375Unit Sheets

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDON	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 4th, 1956

Well No. 7 is located 1100 ft. from N line and 1460 ft. from E line of sec. 6NW/4 NE/4 Sec. 6
(1/4 Sec. and Sec. No.)25N
(Twp.)7W
(Range)N.M.P.M.
(Meridian)Ballard
(Field)Rio Arriba
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6882 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-30-56 TD 2778' RKB. Set 66 joints 2750' of 5-1/2" OD 15.5# J-55 casing at 2742' with 100 sacks cement.

4- 5-56 Pressured up on casing to 1000#. No pressure decrease in 50 minutes.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company BENSON-MONTINAddress 405 1/2 West BroadwayFarmington, New MexicoBy Albert R. GreenTitle Field Superintendent

RECEIVED
MAY 7 1958
U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

