



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS RD. - AZTEC

87410

LAND COMMISSIONER
PHIL R. LUCERO

DIRECTOR
JOE D. RAMEY



STATE GEOLOGIST
EMERY C. ARNOLD

October 7, 1976

Mr. William Dawson
Northwest Production Corp.
c/o El Paso Natural Gas Co.
P. O. Box 990
Farmington, New Mexico

Re: Northwest Production Corp.
Jicarilla 117 E #2
H-33-26N-3W

Dear Mr. Dawson:

The attached packer-leakage test report for the subject well indicates communication between the producible zones.

You are hereby directed to take immediate action to cause the well to comply with Rule 112-A, Section VI and the order authorizing the dual completion.

If there are questions, Please contact us.

Yours very truly,

A. R. Kendrick
Supervisor, District #3

ARK:mc

Attach.


xc: Oil Conservation Commission
Santa Fe, New Mexico

NEW MEXICO OIL CONSERVATION COMMISSION
NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator Northwest Production Corp.			Well Name and Number Jicarilla 117E #2 (PM)		
Location of Well Unit H Sec. 33 Twp. 26 Rge. 3			TYPE OF TEST 1976	Annual - (Give Year)	Initial - (Give Date)
UPPER COMPLETION	Reservoir or Pool PC	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	☐ NEW ☐ OWWO	Production String ☐ CASING ☐ TUBING
LOWER COMPLETION	Reservoir or Pool MV	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT		Production String ☐ CASING ☒ TUBING

Date	Upper Zone		Lower Zone		
	Shut-In		Shut-In	Flow Test	
	Casing	Tubing	Tubing	Tubing	Flow Rate
9-20-76	327	327	327		
9-21-76	341	341	341		
9-22-76	351	351	351		
9-23-76	250	250		219	187
9-24-76	246	246		209	156

Remarks:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Operator instructed to repair

APPROVED _____, 19____
NEW MEXICO OIL CONSERVATION COMMISSION

OPERATOR Northwest Production Corp.

BY H. E. McAnally

TITLE Well Test Engineer

DATE 9-28-76

DAYS

1 2 3 4 5

PRESSURE

Psig

700

600

500

400

300

200

100

Both Zones Shut In

MV

Flowing

NORTHWEST PRODUCTION
Annual Packer Leakage Test
1976
Jicarilla 117 E #2 (PM)
Unit H Sec. 33-26-3
Rio Arriba County, N.M.

°PC Zone • MV Zone

