

Jerry E. Faust
P.O. Box 1940, Hobbs, NM 88240
DEPUTY OIL & GAS INSPECTOR
District VII
1300 La Grue St. Santa Fe, NM 87504
MAR 10 1997

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE
(Revised 1/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Approved

Operator: <u>Marathon Oil Co.</u>		Telephone: <u>505-326-2783</u>
Address: <u>P.O. Box 1439 Farmington, N.M. 87499</u>		
Facility Or: <u>Jicarilla Apache well #1</u>		
Well Name		
Location: Unit or Quarter sec <u>D</u> sec <u>33</u> <u>T26N R5W</u> County <u>Rio Arriba</u>		
Pit type: Separator ☐ Dehydrator ☐ Other <u>wellhead blowdown pit</u>		
Land Type: BLM ☐ State ☐ Fee ☐ Other <u>Jicarilla Apache</u>		
Pit Location: (Attach diagram)	Pit dimensions: length <u>15'</u> , width <u>15'</u> , depth <u>4'</u>	
	Reference: wellhead ☒ , other ☐	
	Footage from reference: <u>33'</u>	
	Direction from reference: ☐ Degrees ☐ East North <u>X</u> of ☐ West South ☐	
Depth To Ground Water: (Vertical distance from contaminants to seasonal high water elevation of ground water)	Less than 50 feet (20 points) 50 feet to 99 feet (10 points) Greater than 100 feet (0 Points) <u>0</u>	
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than 1000 feet from all other water sources)	Yes (20 points) No (0 points) <u>0</u>	
Distance To Surface Water: (Horizontal distance to perennial lakes, ponds, rivers, streams, creeks, irrigation canals and ditches)	Less than 200 feet (20 points) 200 feet to 1000 feet (10 points) Greater than 1000 feet (0 points) <u>0</u>	
RANKING SCORE (TOTAL POINTS):		<u>0</u>

MAR-21-1994 20:34

(505) 966-1094

RECEIVED
MAR - 6 1997

OIL CON. DIV.
DIST. VII

Remediation Method: Excavation ☒ Approx. cubic yards 0
(Check all appropriate sections) Landfarmed ☐ Insitu Bioremediation ☐
Other ☐

Remediation Location: Onsite ☐ Offsite ☐
(ie. landfarmed onsite, name and location of offsite facility)

General Description of Remedial Action: No remedial action required

Ground Water Encountered: No ☒ Yes ☐ Depth ☐

Final Pit:
Closure Sampling:
(if multiple samples, attach sample results and diagram of sample locations and depths)

Sample location middle of pit

Sample depth 4'

Sample date 8-30-96 Sample time 8:00 A.M.

Sample Results

Benzene(ppm) ☐

Total BTEX(ppm) ☐

Field headspace(ppm) 20

TPH 2.8

Ground Water Sample: Yes ☐ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF

DATE 10-22-96


SIGNATURE Gary W. Donaghey PRINTED NAME Gary W. Donaghey
AND TITLE Production Supervisor

NOTES/REMARKS/NOTAS

NON VULNERABLES
AFE 661596

Jicarilla #1

Sample 4' Deep - 20 ppm
pit 15' x 15' x 4'



EPA METHOD 8015 Modified
Nonhalogenated Volatile Organics
Total Petroleum Hydrocarbons


Client:	Marathon Oil Co..	Project #:	95047
Sample ID:	Jicarilla #1	Date Reported:	09-03-96
Laboratory Number:	A519	Date Sampled:	08-30-96
Chain of Custody No:	4865	Date Received:	09-03-96
Sample Matrix:	Soil	Date Extracted:	09-03-96
Preservative:	Cool	Date Analyzed:	09-03-96
Condition:	Cool and Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	0.9	0.2
Diesel Range (C10 - C28)	1.9	0.1
Total Petroleum Hydrocarbons	2.8	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, July 1992.

Comments: Jicarilla Apache, Jicarilla #1, Sample #1.


Analyst


Review

#1


10



73'

Jicarilla
#1
wellhead

meter
House



production
unit

5