



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 079266  
Unit Vaughn

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

RECEIVED  
JAN 8 1960  
U. S. GEOLOGICAL SURVEY  
FEDERAL BUREAU OF REVENUE

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 1900 ft. from S line and 690 ft. from W line of sec. 32  
N/4 Sec. 29 (1/4 Sec. and Sec. No.) 29 (Twp.) 6N (Range) T.4N.R.4E (Meridian)  
So. Blanco N. C. (Field) Rio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5742 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud date 10-29-59

On 10-30-59 Total Depth 133'.

Ran 4 joints of 5 5/8", 32#, J-55 casing (117') set at 127' with 70 sacks regular cement, 2% Gel, 2% Calcium Chloride, 1/2 cu. ft. Strata-Crete 6 /sk circulated to surface.

Held 500 / 30 minutes.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Permington, New Mexico

By ORIGINAL SIGNED A.M. SMITH

Title Petroleum Engineer