

(SUBMIT IN TRIPLICATE)

Indian Agency Maricopa Indian

Contract # 99 Trust 100

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. Maricopa #3

SUNDRY NOTICES AND REPORTS ON WELLS

AUG 11 1957

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 8, 1957

Well No. 4 is located 970 ft. from S line and 970 ft. from W line of sec. 23

Section 23
(34 Sec. and Sec. No.)

24-N
(Twp.)

3-N
(Range)

N.M.P.M.
(Meridian)

Maricopa
(Field)

Maricopa
(County or Subdivision)

Arizona
(State or Territory)

The elevation of the derrick floor above sea level is 1000 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

After setting 2200' of 5 1/2" liner on bottom at 4200' with 240 on cement.
Run Temperature Survey top of cement at 3770'. Bottomed top of 5 1/2" liner
with 240 on cement. Tested top of 5 1/2" liner with 1000 / for 30 minutes.
Tested OK. No break.

ILLEGIBLE



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company MARICOPA PETROLEUM COMPANY

Address P.O. Box 433

MIDLAND, TEXAS

By R. Y. Berman

Title R. Y. Berman
Division Superintendent

