

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Federal Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator El Paso Natural Gas Company	8. Farm or Lease Name Sanchez
3. Address of Operator Box 990, Farmington, New Mexico - 87401	9. Well No. 1 (P&A)
4. Location of Well UNIT LETTER J 1650 FEET FROM THE South 1650 FEET FROM East 20 LINE, SECTION 26N TOWNSHIP 6W RANGE 6W NMPM.	10. Field and Pool, or Wildcat So. Blanco P. C.
15. Elevation (Show whether DF, RT, GR, etc.) 6632' GL	12. County Rio Arriba

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned as follows:

Spotted a 30 sack cement plug on bottom to cover open hole (2895 - 2990').

Perforated 4 holes at 2350' (base of Ojo Alamo), spotted a 50 sack cement plug across perfs. at 2350' and squeezed.

Shot off 5 1/2" casing at 919', spotted a 30 sack cement plug on top of casing stub at 919', pulled casing.

Spotted a 30 sack cement plug at base of surface casing.

Placed a 10 sack cement plug at surface w/a 4' x 4" P & A marker. P&A completed 10-7-69.

A Sundry Notice will follow when location is cleaned up.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed **F. H. WOOD**

SIGNED _____ TITLE **Petroleum Engineer** DATE **10-31-69**

APPROVED BY **Emmy C. Chavez** TITLE **Sgt. Port** DATE **11-4-69**

CONDITIONS OF APPROVAL, IF ANY:

