X

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Indian Agency	Lila
Allottee Jicarilla	Tribal
Loase No. Contract	110

SUNDRY N	OTICES A	ND REP	ORTS ON	WELLS	
NOTICE OF INTENTION TO DRILL	SSHUT-OFF	SUBSEQUENT SUBSEQUENT SUBSEQUENT SUBSEQUENT	REPORT OF WATER REPORT OF SHOOTI REPORT OF ALTERII REPORT OF REDRIL REPORT OF ABANDO	NG OR ACIDIZING NG CASINGLING OR REPAIR	
NOTICE OF INTENTION TO PULL OR ALTE NOTICE OF INTENTION TO ABANDON WEI (INDICATE A)			ARY WELL HISTORY.		
			March 2	Oth	, 19 <u>. 57</u>
Vell No. 1-1 is locate	ed 1520_ft. from	$n \begin{Bmatrix} \blacksquare \\ S \end{Bmatrix}$ line and	d 1600 ft. fr	om $\left\{ egin{array}{c} lackbox{\mathbb{K}} \ lackbox{\mathbb{K}} \end{array} \right\}$ line of	sec. 20
NE/4 SH/4 Sec. 20 (34 Sec. and Sec. No.)		5W (Range)		州人	For p
Vildest (Field)	County or	Arriba Subdivision)	_ f ny	(State of The ton	<u> </u>

The elevation of the derrick floor above sea level is 6717... ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of pro-ing points, and all other important proposed work) nudding jobs, cement-

TD 32141 RKB. Set 98 joints 32221 of 5-1/2" OD 15.5# J-55 Smls. Casing at 32131 RKB with 150 sacks coment. 3-13-57

Temperature survey showed top of cement at 21301.

Pressured up on casing to 1000#. No pressure decrease 3-15-57 in one hour.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company RL PASO NATURAL GAS COMPANY	
Address Box 997	Eld Well
Farmington, New Mexico	By free Coals
	Title Senior Petroleum Engineer