



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 04-008
Unit Letter

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	X
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Sept. 10, 1963, 19 63

Well No. 1 is located 370 ft. from N line and 1650 ft. from E line of sec. 15

1/4 (1/4 Sec. and Sec. No.) ec 15 (Twp.) 1 (Range) N (Meridian)

Undesignated (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 7214 ft. ground

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Logued 5-27-63, ran 650' of 2" csg., cemented with 100 sacks, circulated to surface. Drilled to a T.D. of 1781 in Rd., encountered fresh water with slight dead oil scum. Potted 37 sacks cement from 2781 to 2450 through tubing. Set 4 1/2 production string at 2175 cemented with 40 sacks ran 2" tubing to 2200. Well now shut in for fluid build up. Will start pump testing 10/1/63.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Harold O'Connor

Address 300 Carlisle S.E.

H/bug. N.M.

By Harold O'Connor
Title Operator