

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **SE 079304**
Unit _____
Sanchez #1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


Well No. **Sanchez #1** is located **360** ft. from **N** line and **660** ft. from **W** line of sec. **24**
24 (Sec. and Sec. No.) **26N** (Twp.) **6W** (Range) **N10PM** (Meridian)
South Blando (Field) **Die Arriba** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **6672** ft. **U.S.**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-21-60 - Plug and cement drilled out to 7630'.
6-23-60 - Underreamed to 7650'.
6-24-60 - Ran 5" 15# 3-35 casing to 7630'. Cemented with 550 sacks 12% bentonite cement, followed by 150 sacks neat. All cement contained 12% Gilsenite per sack. Plug down at 11:30 P.M., June 24, 1960.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Cauldins Oil Company**

Address **P. O. Box 700**

Farrington, New Mexico

By *[Signature]*
Title **Production Manager**