

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 03733
Unit Brush

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

10-17, 1958

Well No. 20-310 is located 265 ft. from S line and 1125 ft. from E line of sec. 13


26 1/4 (Sec. and Sec. No.) 26 (Twp.) 7 (Range) N 100 W (Meridian)
Co. 1 (Field) Co. 1 (County or Subdivision) N. M. (State or Territory)

The elevation of the derrick floor above sea level is 6155 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled: 0 at 10-16-58
Cemented 117' 8 5/8" 24- 3-35 casing 127'
100 sacks. Cement Circulated.
Plug down 2:00 PM 10-16-58



ILLEGIBLE

I understand

the Geological Survey before operations may be commenced.

Company Caulkin Oil Company

Address P.O. Box 67

Farmington, New Mexico

By [Signature]

Title Field Rep.