

(SUBMIT IN TRIPLICATE)

Indian Agency Neah

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Marilla Tribal

Lease No. Contract 109

			●

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT: NOTICE, OR OTHER DATA)

July 29th 19 58

Well No. 12-6 is located 1025 ft. from N
S line and 1065 ft. from E
W line of sec. 13

EE/4 EE/4 Sec. 13
(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

H.M.P.M.
(Meridian)

S. ELANDER PC INT.
(Field)

No Affix
(County or Subdivision)

New Mexico
(State or Territory)


The elevation of the derrick floor above sea level is 7199 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

5-29-58 To 3938' MMH. Set 105 joints 3930' of 5-1/2" OD 15.5# J-55 casing at 3934' with 100 sacks cement. Temperature survey showed top of cement at 3700'.

6- 8-58 Pressured up on casing to 1000#. No pressure decrease
in one hour.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **EL PASO NATURAL GAS COMPANY**

Address Box 997

Farmington, New Mexico

By D C Davidson

Title **Petroleum Engineer**

