

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

SF 079083

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. CIL WELL ☐ GAS WELL ☒ OTHER P & A

2. NAME OF OPERATOR

ADOBE RESOURCES CORPORATION

3. ADDRESS OF OPERATOR Brana Corporation

320 Gold Ave. SW, #1223 First Interstate Bldg., Alb., NM 87102

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1650' from south line

1650' from east line

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6124 DF

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Scott D

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

South Blanco PC

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

14-26N-7W-NMPM

12. COUNTY OR PARISH 13. STATE

Rio Arriba

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other) Restoration Report

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Final restoration and seeding of location:

1. All fences, meter run and meter house, deadmen, flowlines, debris and trash has been removed from location.
2. All fluids have been disposed of.
3. All pits have been filled and the edges of the pad has been shaped to conform to the natural terrain.
4. Pad was leveled, ripped and disked with a maintainer.
5. Access road was waterbarred, disked and blocked off with eathern berms. Waterbars were placed on the road.
6. Road and pad were seeded on July 19, 1988 with BLM Seed Mix No. 1.
7. Seeding was done with a drill and followed with a drag and roller in conformance with BLM Reseeding and Abandonment specifications.

Disturbed area (Pad and Road) is approximately  $2\frac{1}{2}$  acres.

All rehabilitation stipulations have been completed on July 19, 1988.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Morris B. Jones, Engineer

DATE July 20, 1988

(This space for Federal or State office use)

JUL 22 1988

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

FARMINGTON RESOURCE AREA  
FARMINGTON, NEW MEXICO

NMOCC

\*See Instructions on Reverse Side