(Â)	ril 19	52)	
		x	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

indian	Assner	Jicarilla
TIMEST WEST	vEsuch	

Allottee Jicarilla Tribel
Lease No. Contract 110

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO TEST WATER SHUT-OFF	<u> </u>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
INTICE OF INTENTION TO GLOOT OR LODITE	IR A JOET
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	nec 3 0 1957
NOTICE OF INTENTION TO PULL OR ALTER CASING	Fennal Cillian
IOTICE OF INTENTION TO ABANDON WELL	WED TO THE
	Maloni
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)	
December 50th	
ell No. 13-J is located 860 ft. from S line and 1587 ft. from E line $N/4$ 38/4 Sec. 17 50 N.M.P.M.	e of sec. <u>17</u>
(% Sec. and Sec. No.) (Twp.) (Range) (Meridian)	
. Blance PC Ext. Ric Arriba Hew N	lexico
(Field) (County or Subdivision) (State or Terr	itory)
e elevation of the derrick floor above sea level is 6606 ft.	
ate names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate m ing points, and all other important proposed work)	
J-55 casing at 3171 with 100 speks coment.	
J-55 casing at 3171 with 100 speks coment. Temperature survey showed top por coment at 2	:4801 .
J-55 casing at 3171' with 100 seeks coment. Temperature survey showed top por coment at 2 2-18-57 Pressured up on casing to 1000%. No pressur	
J-55 casing at 3171 with 100 speks cement. Temperature survey showed top of cement at 2 2-18-57 Pressured up on casing to 1000%. No pressurin one hour. I understand that this plan of work must receive approval in writing by the Geological Survey before operations in	:4801 .
J-55 casing at 3171 with 100 speks coment. Temperature survey showed top of coment at 2 2-18-57 Pressured up on casing to 1000%. No pressurin one hour. I understand that this plan of work must receive approval in writing by the Geological Survey before operations in	:4801 .
J-55 casing at 3171 with 100 seeks coment. Temperature survey showed top po! coment at 2 2-18-57 Pressured up on casing to 1000%. No pressur in one hour. [understand that this plan of work must receive approval in writing by the Geological Survey before operations in mpany KL PASO NATURAL GAS COMPANY	:4801 .