

**(SUBMIT IN TRIPLICATE)**

Indian Agency --- **Jicarilla**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee Marilla Tribal

Lease No. Contract 109

		三	

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	2
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 30th, 1958

Well No. 9-P is located 1190 ft. from 

S
---

 line and 1550 ft. from 

E
W

 line of sec. 15

**SEC. 4 SEC. 4 Sec. 15**  
(1/4 Sec. and Sec. No.)

**26th**  
(Twp.)

250  
(range)

(Meridian)

**S. Blanco PC Ext.**  
(Field)

**File Arrive**  
County or Subdivision)

**New Mexico**  
(State or Territory)


The elevation of the derrick floor above sea level is 6636 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6-24-58 TD 3279' NEM. Set 79 joints 3269' of 5-1/2" OD 15.5# J-55 casing at 3270' with 100 sacks cement. Temperature survey showed top of cement at 2550'.

7-13-58 Pressured up on casing to 1000#. No pressure decrease in one hour.



**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company **EL PASO NATURAL GAS COMPANY**

Address **Box 997**

**Farmington, New Mexico**

By

### Title

**Petroleum Engineer**

