

(SUBMIT IN TRIPLICATE)

Indian Agency ----- **Jicarilla**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Jicarilla Tribal

Lease No. **Contract 110**

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Sandfrac Treatment

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 26th....., 1957

Well No. 9-J is located 1155 ft. from S line and 860 ft. from W line of sec. 18

SM/4 SM/4 Sec. 18
(1/4 Sec. and Sec. No.)

26N
(Twp.)

5W
(Range)

N.M.P.M.
(Meridian)

S. Blanco PC Ext.
(Field)

Rio Arriba
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6590 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12- 5-57 TD 3131'. Cleaned out to 3101'. Perforated 3014-3028' and 3044-3074' with 4 shots per foot. Sandfraced with 26,600 gallons water and 30,000# sand, flushed with 3,400 gallons water. Breakdown pressure 3000#, treating pressure 1500#, average injection rate 44 barrels per minute.

12- 7-57 After 18 hour blow flowing 2,309 MCF/day.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company EL PASO NATURAL GAS COMPANY

Address Box 997

Farmington, New Mexico

By DC Phunhor

Title Petroleum Engineer

100-100000-100000

