



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 079124
Unit _____
(SEE CH "C")

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	X	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 27, 1962

Well No. D-389 is located 1650 ft. from S line and 1190 ft. from W line of sec. 13

SW 1/4 Sec. 13 26N 6W N40W
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Basin Dakota Rio Arriba N. M.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6726 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding, cementing points, and all other important proposed work)

TD 7750. Ran 4 1/2"-11.6#-J-55 Smls. casing to 7727 and cemented as follows:

1st. stage: Through casing shoe with 150 sks. galcement containing 12% gilsonite per sack. Followed by 100 sks. latex cement. Casing rotated during this stage. Plug down at 5:45 AM 6-27-62.

2nd. stage: Through Howco multi stage cementing collar at 5573, with 570 sks. 12% galcement, containing 12% gilsonite per sack. Had full returns during this stage. Cementing collar closed with 3000# pressure. Had no back flow when pressure was released. Casing will be tested with 4000# pressure satisfactorily before perforating.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Caulkins Oil Co.

Address Box 780

Farmington, N.M.

By _____

Title Supt.

