

RECEIVED

MAR 24 1993

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OIL CON. DIV.,
DIST. 3

SF-079184

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 3160-3 for such proposals)

Indian, Allottee or Tribe Name

7. Unit Agreement Name

1. Oil Well [] Gas Well [] Other []
GAS WELL

8. Patch or Lease Name

BREECH "C"

2. Name of Operator:

Caulkins Oil Company

9. Well No.

389

3. Address of Operator:

(505) 632-1544

P.O. Box 340, Bloomfield, NM 87413

10. Field or Wildcat Name

BASIN DAKOTA

4. Location of Well (Report Location Clearly)

1650' F/S 1190' F/W

11. Sec. T.R.M. or Blk and Survey or Area

SEC. 13-26N-6W

14. API No.:

300390647700-S1

Elevation (show BP, RT and GR)

6726 DF

12. County or Parish

Rio Arriba

13. State

NM

16. Intention To: Repair casing
Subsequent Report:

17. Describe Proposed or Completed Operations:

3-12-93 Tests conducted on this well indicate well has recovered from casing failure.

We intend to pull tubing and packer then set wire line bridge plug at approximately 6500'.

Logs will be run to determine top of cement. During repairs sufficient cement will be used to cement casing to surface.

BLM will be notified prior to any cementing.

No new surface to be disturbed.

Estimated starting date - April 5, 1993.

RECEIVED
BLM
MAR 17 AM 11:34
500 FARMINGTON, NM

NOTE: The format is issued in lieu of U.S. BLM Form 3160-5

18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT

SIGNED: Robert L. Verquer
ROBERT L. VERQUER

TITLE: Superintendent DATE: 03/12/93

APPROVED BY: _____ TITLE: _____ DATE: _____

CONDITIONS OF APPROVAL, IF ANY

APPROVED

MAR 22 1993

DISTRICT MANAGER