

Otis Sub-Surface Pressure Report



15-213

Field Jicrilla Well Report No. 40793

Operator Northwest Prod. Corp.

Address 204 North Orchard

Lease E Well No. 11-15 (11/4 Tubin;)
Picturecliff

Date 11-15-57 Status of Well _____

DEPTH	EXTENSION	PRESSURE	INTERVAL	GRADIENT, # FT.
<u>0</u>	<u>011</u>	<u>11</u>		
<u>1000</u>	<u>.181</u>	<u>180</u>	<u>1000</u>	<u>.180</u>
<u>2000</u>	<u>.373</u>	<u>372</u>	<u>1000</u>	<u>.372</u>
<u>3000</u>	<u>.798</u>	<u>795</u>	<u>1000</u>	<u>.423</u>
<u>3500</u>	<u>1.012</u>	<u>1008</u>	<u>500</u>	<u>.426</u>
<u>3737</u>	<u>1.121</u>	<u>1111</u>	<u>237</u>	<u>.438</u>

Casing Pressure _____ Tubing Pressure 11#

Fluid Level _____ Water Level _____

Previous Test Date _____ Previous B.H.P. _____

NORTHWEST PRODUCTION


Change in B.H.P. _____

Previous Bottom Hole Temperature _____

Present Temperature _____

Change in Temperature _____

NOV 22 1957



Instrument Type and No. Amerada #111140-N Range 0-2000

Date of Latest Calibration 9/19/57

Pressure Run by Strong Interpreted by Same