UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5.	LEASÆ	
	NM 03553	

GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)		
1 -11	Breech D	
1. oil gas X other	9. WELL NO.	
2. NAME OF OPERATOR	239	
Caulkins Oil Company	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	South Blanco Pictured Cliffs	
P.O. Box 780 Farmington, New Mexico	11. SEC., T., R., M., OR BLK. AND SURVEY OR	
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA	
below.)	Section 15 26 North 6 West 12. COUNTY OR PARISH 13. STATE	
AT SURFACE: 990° F/N & 1650° F/E AT TOP PROD. INTERVAL:		
AT TOTAL DEPTH: Same Same	Rio Arriba New Mexico	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
	6503 DF	
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF		
FRACTURE TREAT		
REPAIR WELL	(NOTE: Report results of multiple completion or zone	
PULL OR ALTER CASING	change on Form 9–330.)	
MULTIPLE COMPLETE MAY L 1 1987		
CHANGE ZONES	WWY PARTY OF THE PROPERTY OF T	
ABANDON* U. S. GLUB JORGAL SE (other) PARKWINGTON, N.	M. The SECOND SECOND SECOND	
including estimated date of starting they proposed work. If well is demeasured and true vertical depths for all markers and zones pertined. It is proposed to pull plugged tubing, clean	mt to this work:	
The proposed starting date is 6-02-82.		
5		
No new surface to be disturbed.		
	그 그 그는 학교육을 함께 불리하다	
	그는 내가 하는 그 원활하겠다. 현실 선생님들이 모든 모든	
Subsurface Safety Valve: Manu. and Type	Set @ Ft.	
18. I hereby contry that the foregoing is true and correct		
SIGNED Superintend	dent DATE 5-06-82	
(hi) space for Federal or State of	ffice use)	
CONDITIONS OF APPROVALLY ANY; 198?	DATE	
FOYJAMES F. SIMS DISTRICT ENGINEER		

See Instructions on Reverse Side