Form 9-331a (Feb. 1951)

	x	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Approval expires 12-31-60.
Land Office Fe
Loase 104 03733
Unit
Breech"

Budget Bureau No. 42-R358.4

OTICE OF INTENTION TO DR OTICE OF INTENTION TO CH OTICE OF INTENTION TO TE OTICE OF INTENTION TO RE OTICE OF INTENTION TO SH OTICE OF INTENTION TO PU OTICE OF INTENTION TO AB	ANGE PLANS	SUBSEQUENT REPO SUBSEQUENT REPO SUBSEQUENT REPO SUBSEQUENT REPO SUBSEQUENT REPO SUPPLEMENTARY V	RT OF WATER SHUT-OFF. RT OF SHOOTING OR ACI RT OF ALTERING CASING RT OF RE-DRILLING OR I RT OF ABANDONMENT	IDIRING GEOLOGICAL INCTELL NEW REPAIR
	INDICATE ABOVE BY CHEC	K MARK NATURE OF REPORT, NO	ICE, OR OTHER DATA)	
	`		September 19,	
N 3:0–224 is	`	. from ${N \atop S}$ line and 140	September 19, ft. fram $\begin{bmatrix} E \\ W \end{bmatrix}$	
1 N3.D-224 is 4 NE/4 13 (1/2 Sec. and Sec. No.)	locate 365 ft 2611	. from ${N \atop S}$ line and N	September 19, ft. fram $E \setminus W$	
N3D-224 is 4 N2/4 13	locate ³⁶⁵ ft 26N (Twp.) Rio Arrib	. from ${N \atop S}$ line and N	ft. frank EW	

Packer leakage tests made 7-1-60 thru 7-24-60 indicated communication between Mesa Verde and Greenhorn sones. On September 16 and 17 the 1st tubing and Otis cheke separating these two sones were pulled, repaired and re-run to 5153. Tests made September 18 indicate that the sones are now satisfactorily separated. New deliverability and packer leakage tests as required by State of New Mexico, will be made soon as possible.

	I understand that this plan of work must receive approval in writing Company Caulkins Cil Company						
	Address F. O. Box 780			_1			
		Farmington, New Mexico			By Incush Snay Title Troduction Superintendent		
					Title Troduction Superintendent		
ISGS	5	CEV 1	TOM	•	GPO 918507		