



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. SM 03356
Unit Brook "C"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 10, 1960

Well No. SM-241 is located 990 ft. from [N] line and 990 ft. from [E] line of sec. 14

14 26N 6W SMN
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Blanco Pico Bio Arriba New Mexico
tural (Oil) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6622 ft. W

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

2-4-60 - Frac'd w/24,276 gallons water and 50,000 10-20 sand.
flushed w/1192 gallons water.

ISP = 1600'

IF = 1400'

IF = 1000'

API = 40.0 API

ASW = 21 per gal.

Well on vacuum in 3 hours.

can 1" tubing to 3033'.

2-5-60 - request for Allowable has been made to OCS on their 100-104



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Caulkins Oil Company

Address Box 967

Barmin-ton, New Mexico

By Charles Verguer

Title Production