

EPFS


EL PASO FIELD SERVICES

FIELD PIT SITE ASSESSMENT FORM

GENERAL	Meter: <u>70510</u> Location: <u>BURNS #4</u> Operator #: _____ Operator Name: <u>CENTRAL RESOURCE</u> / <u>L</u> District: <u>BALLARD</u> Coordinates: Letter: <u>D</u> Section <u>9</u> Township: <u>26</u> Range: <u>7</u> Or Latitude _____ Longitude _____ Pit Type: Dehydrator _____ Location Drip: <u>X</u> Line Drip: _____ Other: _____ Site Assessment Date: <u>6.16.94</u> Area: <u>07</u> Run: <u>51</u>
SITE ASSESSMENT	NMOCD Zone: (From NMOCD Maps) Inside ☒ (1) Outside ☐ (2) Land Type: BLM ☒ (1) State ☐ (2) Fee ☐ (3) <i>Denny L. Felt</i> DEPUTY OIL & GAS INSPECTOR SEP 10 1996 Depth to Groundwater Less Than 50 Feet (20 points) ☒ (1) 50 Ft to 99 Ft (10 points) ☐ (2) Greater Than 100 Ft (0 points) ☐ (3) Wellhead Protection Area : Is it less than 1000 ft from wells, springs, or other sources of fresh water extraction? , or ; Is it less than 200 ft from a private domestic water source? ☐ (1) YES (20 points) ☒ (2) NO (0 points) Horizontal Distance to Surface Water Body Less Than 200 Ft (20 points) ☐ (1) 200 Ft to 1000 Ft (10 points) ☒ (2) Greater Than 1000 Ft (0 points) ☐ (3) Name of Surface Water Body <u>CANON LARGO</u> (Surface Water Body : Perennial Rivers, Major Wash, Streams, Creeks, Irrigation Canals, Ditches, Lakes, Ponds) Distance to Nearest Ephemeral Stream ☐ (1) < 100' (Navajo Pits Only) ☐ (2) > 100' TOTAL HAZARD RANKING SCORE: <u>30</u> POINTS
REMARKS	Remarks : <u>ONLY PIT ON LOCATION. PIT IS DRY. LOCATION IS IN LARGO CANYON SOUTH OF LARGO WASH. REDLINE AND TPO CONFIRMED LOCATION IS INSIDE V.2.</u>

ORIGINAL PIT LOCATION

Original Pit : a) Degrees from North 165° Footage from Wellhead 96'
 b) Length : 22' Width : 17' Depth : 3'



REMARKS :

TOOK PICTURES AT 2:59 P.M.

END DUMP

Completed By:

Robert Thompson

Signature

6-16-94

Date

FILL PIT REMEDIATION/CLOSURE FORM

GENERAL

Meter: 70510 Location: BURN #4
 Coordinates: Letter: D Section 9 Township: 26 Range: 7
 Or Latitude _____ Longitude _____
 Date Started : 7-21-94 Area: 07 Run: 51

FIELD OBSERVATIONS

Sample Number(s): KP 142
 Sample Depth: 12 Feet
 Final PID Reading 060 PID Reading Depth 12 Feet
 Yes No
 Groundwater Encountered ☐ (1) ☒ (2) Approximate Depth _____ Feet

CLOSURE

Remediation Method :
 Excavation ☐ (1) Approx. Cubic Yards 0
 Onsite Bioremediation ☐ (2)
 Backfill Pit Without Excavation ☒ (3)
 Soil Disposition:
 Envirotech ☒ (1) ☐ (3) Tierra
 Other Facility ☐ (2) Name: _____
 Pit Closure Date: _____ Pit Closed By: _____

REMARKS

Remarks : Some line markers. Pit looked clean
dug a sample hole. PID 060 closed pit

Signature of Specialist: Kelly Pahlke



FIELD SERVICES LABORATORY

ANALYTICAL REPORT

PIT CLOSURE PROJECT - Soil

SAMPLE IDENTIFICATION

SAMPLE NUMBER:

KP 142

Lab ID

945751

MTR CODE : SITE NAME:

70510

N/A

SAMPLE DATE : TIME (Hrs):

7-26-94

1530

SAMPLED BY:

N/A

DATE OF TPH EXT. ANAL:

7-26-94

7-26-94

DATE OF BTEX EXT. ANAL:

7/27/94

7/27/94

TYPE : DESCRIPTION:

VG

Fine Brown Sand

REMARKS:

RESULTS

PARAMETER	RESULT	UNITS	QUALIFIERS			
			DF	Q	M(g)	V(ml)
BENZENE	LO.025	MG/KG	1			
TOLUENE	<0.025	MG/KG	1			
ETHYL BENZENE	<0.025	MG/KG	1			
TOTAL XYLENES	<0.025	MG/KG	1			
TOTAL BTEX <0.10	56.4 56.4	MG/KG				
TPH (E18.1)	56.4	MG/KG			2.11	28
HEADSPACE PID	60	PPM				
PERCENT SOLIDS	96.1	%				

TPH is by EPA Method 18.1 and BTEX is by EPA Method 8020 -

The Surrogate Recovery was at
Narrative:

85

% for this sample All QA/QC was acceptable.

AT-I results attached.

DF = Dilution Factor Used

0 D

Date:

8/14/94




Analytical **Technologies**, Inc.

2709-D Pan American Freeway, NE Albuquerque, NM 87107
Phone (505) 344-3777 FAX (505) 344-4413

ATI I.D. 407410

July 29, 1994

El Paso Natural Gas Co.
P.O. Box 4990
Farmington, NM 87499



Project Name/Number: PIT CLOSURE 24324

Attention: John Lambdin

On 07/27/94, Analytical Technologies, Inc., (ADHS License No. AZ0015), received a request to analyze **non-aqueous** samples. The samples were analyzed with EPA methodology or equivalent methods. The results of these analyses and the quality control data, which follow each set of analyses, are enclosed.

If you have any questions or comments, please do not hesitate to contact us at (505) 344-3777.

Letitia Krakowski, Ph.D.
Project Manager

H. Mitchell Rubenstein, Ph.D.
Laboratory Manager

MR:jt

Enclosure

GAS CHROMATOGRAPHY RESULTS

TEST : BTEX (EPA 8020)
 CLIENT : EL PASO NATURAL GAS CO. ATI I.D.: 407410
 PROJECT # : 24324
 PROJECT NAME : PIT CLOSURE

SAMPLE ID. #	CLIENT I.D.	MATRIX	DATE SAMPLED	DATE EXTRACTED	DATE ANALYZED	DIL. FACTOR
04	945750	NON-AQ	07/21/94	07/27/94	07/27/94	1
05	945751	NON-AQ	07/21/94	07/27/94	07/27/94	1
06	945752	NON-AQ	07/22/94	07/27/94	07/28/94	1

PARAMETER	UNITS	04	05	06
BENZENE	MG/KG	<0.025	<0.025	<0.025
TOLUENE	MG/KG	<0.025	<0.025	<0.025
ETHYLBENZENE	MG/KG	<0.025	<0.025	<0.025
TOTAL XYLENES	MG/KG	<0.025	<0.025	<0.025

SURROGATE:

BROMOFLUOROBENZENE (%) 89 85 86