


UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office SF

Lease No. 079035-A

Unit NE/4, Section 10



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 12, 1952

Well No. 15-28-135 is located 1050 ft. from N line and 1650 ft. from E line of sec. 10

NW, NE/4 Sec. 10 26N 6W N.M.P.M.
(4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6629 ft. GL.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

Drilled cement plug and tested 7" casing for 3 hours. Ran bailer.
No. water. Casing O.K. Cleaned out to TD 3170'. Gas measured 55 MCF Natural
Killed well with water.

2-7-52 shot with 896 qts. SNG from 3093' to 3170'. Tamped 5' pea gravel
and 92' cal-seal. Shot exploded O.K. Cleaned out to 3081. Ran Schlumber
to see if shot had damaged casing. Casing O. K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Lowry et al Operating Account

Address Room 219

616 East Central Avenue

Albuquerque, New Mexico

By E. R. Richardson
E. R. Richardson
Title Business Manager