

Form 9-231a
(Feb. 1951)


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 079035

Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO REPAIR <u>Plug back</u> <u>XX</u>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ July 12 _____, 1951

Well No. Scott 1 is located 660 ft. from [N] line and 1980 ft. from [W] line of sec. 10

NE 1/4 sec. 10 26 N 6 W N. M. F. M.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wilcox Rio Arriba New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6630 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This was completed in the Wakota Sand, from 7200 to 7473' but oil and gas was not found in commercial quantity necessary for continued production.

Therefore it is requested that we be granted permission to plug back and complete in the TUCITO Sand which is present at 6718 to 6768'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company ROSEHILL & PERTIGER

Address 719 1st Nat'l. Bk. Bldg.,

Dallas, Texas

By [Signature]
A. A. HUNT
Title Supt.

100-100000

100-100000

100-100000

100-100000

100-100000