

(SUBMIT IN TRIPLICATE)

Indian Agency Stonilla

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Allottee \_\_\_\_\_

Lease No. \_\_\_\_\_

Stonilla Contract # 131

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY  
WASHINGTON, NEW MEXICO


Antonia Stonilla  
Well No. 1-2 is located 1000 ft. from S line and 900 ft. from W line of sec. 4  
Sec. 4 (1/4 Sec. and Sec. No.) 2-20N (Twp.) 1-2W (Range) 2-20N-1W (Meridian)  
No. 10000 P.O. (Field) San Antonio (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6998 ft. S.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was cased 8/4/60  
Set 3 1/2" 150' of 7 1/8" surface casing, landed at 142' with 150 sacks cement  
Tested casing with 500 pressure for 30 minutes. No leaks.  
Drilled cement plug 1/4/60  
Tested with 500 pressure for 30 minutes.  
No drop in pressure.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Antonia Stonilla

Address Box # 370

Stonington, New Mexico

By ORIGINAL SIGNED BY JOE C. SALMON

Joe C. Salmon

Title District Superintendent