

Form 9-331a  
(Feb. 1951)

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office San Antonio  
Lease No. 00001  
Unit Sec. 4 15

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November

19

Well No. 1-4-85 is located 170 ft. from N line and 110 ft. from E line of sec. 4  
10 1/4 sec. 4 10 1/4 10 1/4 10 1/4  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
10 1/4 (Field) 10 1/4 (County or Subdivision) San Antonio (State or Territory)

The elevation of the derrick floor above sea level is 620 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well is located in Sec. 4, T. 10 N., R. 10 E., S. 4  
and is expected to be 100 ft. deep. It is a 10 inch diameter well.  
Current circulation.  
Test at 500 ft. surface casing. 600 pressure for 1 hr. did not decrease.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Antonio

Address San Antonio

By San Antonio

Title San Antonio