



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office N M
Lease No. 03551
Unit _____
Derrick "E"

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 27, 1963

Well No. T-61 is located 1925 ft. from N line and 720 ft. from W line of sec. 5

SW 1/4 Section 5 (1/4 Sec. and Sec. No.) 26 N (Twp.) 6 W (Range) N M P M (Meridian)

South Blanco Tostito (Field) Mio Arriba (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6668 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

TU 6890. Cemented 7" OD Casing as follows:

0 to 5873 23# J-55 ST&C Casing

5873 to 6890 26# J-55 ST&C Casing

Cementing details:

(1) Cemented through shoe at 6890 with 150 sacks regular cement followed by 50 sacks latex cement. Had good circulation and free rotation during this stage. Plug down 8:20 PM 3-26-63.

(2) Cemented through Halliburton DV Stage Collar at 5545 with 300 sacks 12% gel cement containing 12# gilsonite per sack and .4% HB-7. Had good circulation during this stage. Closed stage collar with 2200# pressure. Plug down at 12:30 AM 3-27-63.

Used Halliburton Centralizers at 6885, 6765, 5578 and 5510

Used Halliburton Roto Scratchers 6867 to 6797

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Caulkins Oil Company

Address Box 780

Farmington, New Mexico

By Frank Gray

Title Superintendent

