DII	TRIBUTIO	н	
SANTA FF			I
FILE			1
U.S.B.S.			
LAND OFFICE			
TRANSPORTER	OIL OAS		
PRORATION OFFICE		7	
			T

## NEW MEXICO OIL CONSERVATION COMMISSION (Form C-104)

Santa Fe, New Noco

## REQUEST FOR (OIL) - (GAS) ALLOWARLE

New Well

PRORATION O	PPICE	7			Recompletion
OPERATOR	<u> </u>			by the operator before an initial allowable will be assigned to any completed (	Oil or Gas well.
			missad in	OTADRIPLICATE to the same District Unice to which Form C-101 was so	ent. The allow-
		•	i 7.0	in A M on date of completion or recompletion, provided this form is nice of	luring calendar
-anch	f comi	oletion or	recomple	etion. The completion date shall be that date in the case of an on wen when	new oil is deliv-
ered int	n the s	tock tank	s. Gai mu	ist be reported on 15.025 psia at 60° ranrenneit.	
				Denver, Colorado	12/6/63
				(Place)	(Date)
WE AR	E HEF	REBY RE	QUEST	ING AN ALLOWABLE FOR A WELL KNOWN AS:	NIW
Huron	Dril	ling Co	o., Inc	Huron, Well No. 4-4, in. Ny. /	
up.u	(Compa	iny or Ope	rator)	(Lesse)  - 24N - NAPM Tapacito	Pool
• • • • • • • • • • • • • • • • • • • •		, occ	***************	(Lesse) Tapacito Tapacito	
Rio Ai	rriba			County Date Smidded 9/3/63 Date Drilling Completed	
				Elevation 0904iotal bepth 0100	
P	'lease 11	ndicate ic	cation:	Top Oil/Gas Pay 3732 Name of Prod. Form. Pictured (	Cliffs
D	C	В	A	PRODUCING INTERVAL -	
þ		İ	1		
<u></u>	F	G	H	Perforations 3732-461, 3758-781, 3791-38021  Depth Casing Shoe Tubing	3862'
E	F	4	"	Open Hole Casing Shoe Tubing_	3001
Į				OIL WELL TEST -	Choke
L	K	J	I	Natural Prod. Test:bbls.oil,bbls water inhrs,	min- Size
	l	ł		Test After Acid or Fracture Treatment (after recovery of volume of oil equ	al to volume of
	<u></u>		P	Test After Acid or Fracture Treatment (after recovery or tracture areas and a second or fracture areas are a second or fracture areas and a second or fracture areas are a second or fracture areas and a second or fracture areas are a second or fracture areas and a second or fracture areas are a second or fracture areas and a second or fracture areas are a second or fracture areas areas and a second or fracture areas are s are a second or fracture areas areas are a second or fracture areas are a second or fracture areas areas are a second or fracture are	Choke
M	Ŋ	0	F	load oil used):bbls.oil,bbls water inhrs,	
				GAS WELL TEST -	
-	<del></del>			Natural Prod. Test: MCF/Day; Hours flowed Choke	Si ze
	(F00	TAGE)	nting Reg		
Tubing Sir		Feet	nting Reco	Test After Acid or Fracture Treatment: 923 MCF/Day; Hours	flowed 3
312	<del></del>	<del></del>		Choke Size 3/4" Method of Testing: One-point Back Press	ure
12-3	141	3061	300		
12-3	77 =	300	300	Acid or Fracture Treatment (Give amounts of materials used, such as acid, send): Sand/water frac with 100,000 lbs., and 83.390	water, oil, and
8-5	5/8'1	39851	325	gend): Sand/water frac with 100,000 lbs., and 83,390	gals
				Casing Occ.   Tubing Out first new	
1"		3862		Press. 820# Press. 68# oil run to tanks	
				Oil Transporter LaMar Trucking, Inc.	
			<u> </u>	Gas Transporter Southern Union Gas Company	
Remar	ke:			***************************************	
Vemm					arn.
				nformation given above is true and complete to the best of my knowledge.	ULIV.
I	hereby	certify th	nat the in 1964	HURON DRILLING CO. INC	
Approv	redJ	AN D		19 HURON DESTRUCTION OF OPERATOR OPE	V6 1864
			•	By It I Will Coll (	COM-COM
	OIL	CONSE	RVATIO	ON COMMISSION By: (Signature)	DIST. S 🣝
				Title President	Control of the Contro
By: Original Signed Emery					well to:
egen . *	Supe	rvisor Dis	t. # 3	Name	
Title				Address 1575 Sherman - Denver	(80293)
		4		Address	