


Section 1



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R-369.2
Approval expires 12-31-55.

Indian Agency **Jicarilla Tribal**
Contract # **96, Tr. 165**

Allottee _____

Lease No. **Jicarilla "H"**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 13, 1957

Jicarilla "H"
Well No. **4** is located **990** ft. from **[N]** line and **990** ft. from **[E]** line of sec. **1**


Section 1 **24-N 3-W** **N.M.P.M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Blanco **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **Est. 7175** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding, cementing points, and all other important proposed work)

After setting 306' of 10-3/4" Surface Casing on Btm. at 306' W/125 sz/ cement, Circulated. Tested 10-3/4" surface casing with 800 # before and 400 # after drilling Plug. Test OK, No Break.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **MAGNOLIA PETROLEUM COMPANY**

Address **BOX 633**
MIDLAND, TEXAS

By **H. J. Berman**
H. J. Berman
Title **Division Superintendent**

