

X		

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____
Florilla Apache 102
Allottee _____
Lease No. _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____	RECEIVED JUL 25 1963
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____	
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____	
NOTICE OF INTENTION TO ABANDON WELL _____		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

Florilla Apache 102

Farmington, New Mexico, July 24, 1963

Well No. **10** is located **890** ft. from **[N]** line and **1000** ft. from **[W]** line of sec. **4**

10-3/4" casing (Type) **2-5/8" casing** (Type) **2-1/2" casing** (Type)

Basin Dakota (Field) **Elizabethtown** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. (To be reported later)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

The above well was spotted on 7-14-63 and drilled to a total depth of 197'. 10-3/4" casing was set at that depth with 140 sacks Quikstrength containing 25 Calcium Chloride. Cement was circulated to surface. After waiting on cement tested casing with 1000 psi for 30 minutes. Test O.K. Reduced hole to 9-7/8" and resumed drilling.

Drilled to a depth of 4140' and 7-5/8" casing was set at that depth with 140 sacks Quikstrength cement. After waiting on cement tested casing with 2500 psi for 30 minutes. Test O.K. Reduced hole to 6-3/4" and resumed drilling.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Pan American Petroleum Corporation**

Address **P.O. Box 400**

Farmington, New Mexico

Attn: **L. G. Spear, Jr.**

By _____

Title **Petroleum Engineer**



ORIGINAL SIGNED BY
F. H. HOLLINGSWORTH

