

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Cont 110
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla Dulce N.M.
3. ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1595 FSL 900 FWL Unit L		8. FARM OR LEASE NAME Jicarilla "A"
14. PERMIT NO.		9. WELL NO. 7
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6681 Gr.		10. FIELD AND POOL, OR WILDCAT Basin Dakota
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 17, T26N - R5W
		12. COUNTY OR PARISH Rio Arriba
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input checked="" type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Rig up completion unit 9/7/66. Cleaned out to 7637 PBTD. Perforated 7583 - 87, 8 holes, 7594-7604, 20 holes. Frac with 45,000 gals. water and 21,800 # sand. Set bridge plug at 7575. Perforated 7552 - 56 with 8 shots, 7508 - 12 with 20 shots. Frac with 50,000# sand and 95,000 gals. water. Cleaned out to 7637. Ran 2 3/8" EUE tubing set at 7603.

Released rig 9/10/66. Waiting on test.

RECEIVED

SEP 15 1966

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

RECEIVED

SEP 16 1966

OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Harold C. Nichols

TITLE Senior Production Clerk

DATE 9/14/66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

DISTRIBUTION:

5-USGS, 1-Continental, 1-Atlantic, 1-File

*See Instructions on Reverse Side