

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐  
WELL WELL

2. NAME OF OPERATOR

Tenneco Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 1714, Durango, Colorado 81302

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

990' FSL, 1090' FWL

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Cont. 110

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Dulce New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla A

9. WELL NO.

6

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 20, T26N, R5W

12. COUNTY OR PARISH 13. STATE

Rio Arriba New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

6712' GR

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:



TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐WATER SHUT-OFF ☐FRACTURE TREATMENT ☒SHOOTING OR ACIDIZING ☒(Other) ☐

## SUBSEQUENT REPORT OF:

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Cleaned out to 7629' PBTD. Perf 7293-7520. Ran packer to bottom and stuck at 7515'. Pulled tubing and left packer in hole. Pushed fish to bottom of hole. Cut off tubing joint and safety joint. Frac perfs 7293-7520 w/105,000 gals water and 100,000 lbs sand. Released rig 12-24-65. Ran 238 jts 2-3/8" EUE J-55 tubing landed at 7521. Set Xmas tree. Job complete 12-24-65. Will conduct deliverability tests. S.I. waiting on pipeline.



18. I hereby certify that the foregoing is true and correct

SIGNED

*Harold C. Spitz*

TITLE Senior Production Clerk

DATE 12-29-65

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

5 copies USGS, Farmington  
1 copy Continental, Durango  
1 copy Atlantic, Farmington  
1 copy Tenneco file

\*See Instructions on Reverse Side