

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Jicarilla Cont 108	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Jicarilla, Dulce, New Mex.	
3. ADDRESS OF OPERATOR P. O. Box 1714, Durango, Colorado 81301		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  835' FSL 2140' FWL Unit Letter "N"		8. FARM OR LEASE NAME Jicarilla "C"	
14. PERMIT NO.		9. WELL NO. #2	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6942' GR		10. FIELD AND POOL, OR WILDCAT Basin Dakota	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 14, T-26-N, R-5-W	
		12. COUNTY OR PARISH Rio Arriba	
		18. STATE New Mex.	

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☒  
SHOOTING OR ACIDIZING ☒  
(Other) ☐

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Rig up completion rig 10/18/66. Cleaned out to 7964' PBD. Perf 7932-28, 7898-90, 7867-65, 7854-52, 7822-10 w/1 HPF. Frac w/80,000# sand and 80,000 gallons water. Set BP at 7800. Perf 7779-76, 7717-14, 7709-06, 7697-92 w/2 HPF. Frac w/40,000# sand, 40,000 gallons water. Drilled BP and Cleaned out to 7964 PBD. Ran 2-3/8" EUE tubing, landed at 7905. Released rig 10/21/66. WO Test.



18. I hereby certify that the foregoing is true and correct

SIGNED Harold C. Nichols TITLE Senior Production Clerk

DATE October 26, 1966

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

6 USGS  
1 Atlantic  
1 Cont.  
1 File

\*See Instructions on Reverse Side