



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor

Jennifer A. Salisbury

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

August 23, 2001

Mary Corley
Amoco Production Company
PO Box 3092
Houston TX 77253

8E

RE: Jicarilla A 008, P-17-26N-05W, API 30-039-22697

Dear Mrs. Corley:

The Bradenhead test on the above well does not provide the required information. The well is not in compliance with Rule 115.B.

Valves shall be installed and maintained in good working order to permit pressures to be obtained on both casing and tubing....

You are hereby directed to bring the well into compliance with Rule 115.B. before December 1, 2001. and submit a Bradenhead Test Report.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely,

Charlie T. Perrin

Charlie T Perrin
Deputy Oil & Gas Inspector
cperrin@state.nm.us

CTP/mk

CC: Jicarilla Apache Tribe
BLM/Farmington
Well file
CP