

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **NM 03552**
Lease No. **NM 079185**
Unit _____
Router

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 11, 1961

Well No. **PC-297** is located **1650** ft. from **N** line and **990** ft. from **W** line of sec. **22 15**

SW Section 15 **26 N** **6 W** **N M P M**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


South Blanco Pictured Cliffs **Rio Arriba** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **6506** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

10-4-61 Fractured with 50,000# 10-20 sand and 26,796 gallons water. Deliverability test after frac was 813 MCFPD 10-31-61



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Caulkins Oil Company**

Address **Box 780**

Farmington, New Mexico

By

Title **Superintendent**