

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Santa Fe 081222-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Cañada Ojitos Unit

8. FARM OR LEASE NAME

9. WELL NO.

13 (L-27)

10. FIELD AND POOL, OR WILDCAT

West Puerto Chiquito

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 27, T-26N, R-1W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7451' GR

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8- 3-69 TD 6800' RKB. Ran 6805' 7-5/8" OD 26.40# N-80 casing landed at 6799' RKB, cemented with 300 sacks 2% gel, 12½# gilsonite and ¼# flocele per sack, followed with 150 sacks cement, 1% gel, 12½# gilsonite and ¼# flocele per sack.

Temperature survey showed top of cement at 4620'.

8- 4-69 Pressured up on casing to 2000#. No pressure decrease in one hour.



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Vice-President

DATE

8-8-69

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
AUG 12 1969