

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 03551

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Breech "E"

9. WELL NO.

68-E

10. FIELD AND POOL, OR WILDCAT

Otero Chacra
Basin Dakota - Blanco MV

11. SEC., T., R., M., OR BLK. AND
SURVEY OR ARMA

Section 4, 26 North 6 West

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

OCT 03 1985

2. NAME OF OPERATOR

Caulkins Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 780 Farmington, New Mexico 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' F/S and 660' F/W

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, GR, etc.)

6470 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) Commingled Chacra, MV, and Dakota Zones

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Order # R-7981

9-27-85

Pulled 1 1/4" Tubing salvaged same.

Pulled 2 3/8" Tubing with Model "D" Seal Assy.

Re-dressed Seal Assy, then re-ran 2 3/8" Tubing.

Baker Model "AR1" Packer set between Chacra and Mesa Verde Zones.

Reverse Flow Check Valve installed immediately above Seal Assy

and "AR1" Packer.

RECEIVED

OCT 10 1985

OIL CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Charles W. [Signature]

TITLE Superintendent

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE 10-2-85

ACCEPTED FOR RECORD

DATE OCT 08 1985

FARMINGTON RESOURCE AREA

BY *sm*

*See Instructions on Reverse Side

NMOCG