

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT--" for such proposals)		5. Lease <div style="text-align: center;">NM-03551</div>
		6. If Indian, Allottee or Tribe Name
		7. Unit Agreement Name
1. Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> <div style="text-align: center;">GAS WELL</div>		8. Well Name and No. <div style="text-align: center;">BREECH "E" 68</div>
2. Name of Operator: <div style="text-align: center;">Caulkins Oil Company</div>		9. API Well No. <div style="text-align: center;">300392023000-S1</div>
3. Address of Operator: (505) 632-1544 <div style="text-align: center;">P.O. Box 340, Bloomfield, NM 87413</div>		10. Field and Pool, Exploratory Area <div style="text-align: center;">BASIN DAKOTA</div>
4. Location of Well (Postage, Sec., Twp., Rge.) 2360' F/N 1820' F/W, SEC. 4-26N-6W		11. Country or Parish, State Rio Arriba Co., New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION	TYPE OF ACTION	
<input type="checkbox"/> Notice of Intent <input checked="" type="checkbox"/> Subsequent Report <input type="checkbox"/> Final Abandonment Notice	<div style="display: flex; justify-content: space-between;"> <div style="width: 60%;"> <input type="checkbox"/> Abandonment <input type="checkbox"/> Recompletion <input type="checkbox"/> Plugging Back <input type="checkbox"/> Casing Repair <input type="checkbox"/> Altering Casing <input checked="" type="checkbox"/> Other Tubing Repairs </div> <div style="width: 35%;"> <input type="checkbox"/> Change of Plans <input type="checkbox"/> New Construction <input type="checkbox"/> Non-Routine Fracturing <input type="checkbox"/> Water Shut-Off <input type="checkbox"/> Conversion to Injection <input type="checkbox"/> Dispose Water </div> </div>	
17. Describe Proposed or Completed Operations: <div style="margin-top: 20px;"> 9-20-93 Pulled 2 3/8" tubing and discovered approximately 2000' of bad tubing from the surface down. Replaced 93 joints, re-ran tubing and landed at 7319'. Well will be swabbed in and will resume production as soon as possible. </div>		
<div style="border: 1px solid black; padding: 10px; width: fit-content; margin: 0 auto;"> RECEIVED OCT 04 1993 OIL CON. DIV DIST. 3 </div>		
NOTE: The format is issued in lieu of U.S. BLM Form 3160-5		
18. I HEREBY CERTIFY THE FOREGOING IS TRUE AND CORRECT <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> SIGNED: <u>Robert L. Verquer</u> ROBERT L. VERQUER </div> <div style="width: 50%;"> TITLE: Superintendent DATE: 09/23/93 <div style="text-align: right;">ACCEPTED FOR RECORD</div> </div> </div>		
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> APPROVED BY: _____ CONDITIONS OF APPROVAL, IF ANY </div> <div style="width: 50%;"> TITLE: _____ <div style="text-align: right;"> SEP 24 1993 FARMINGTON DISTRICT OFFICE </div> </div> </div>		