Form 3160-5 November 19 Formerly 9-	983)	EPART	UNITED STATES MENT OF THE INT U OF LAND MANAGE	· · · · - · · ·	PLICATE*	Form approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND REPLAL NO. SF 078880	
(Do no			CES AND REPOR	TS ON WELLS plug back to a different reserve such proposals.)	oir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
OIL CAS TO OTHER 2. NAME OF OPERATOR						7. UNIT AGRERMENT NAME Canyon Largo Unit 8. FARM OR LEASE NAME	
El Paso Natural Gas Company 3. ADDRESS OF OPERATOR						Canyon Largo Unit NI	
PO Box 4289, Fa. 1. Location of Well (Report location See also space 17 below.) At surface 930 'S			= ,	•	D	146 10. FIELD AND POOL, OR WILDCAT	
	3	JU J,		JUL 2 5 1984 REAU OF LAND MANAGEM	other f	Ballard Pic.Cliffs 11. SBC, T. B., M., OR BLK. AND SURVEY OR ARMA SOC. O. T. 25 N. D. 7 W.	
14. PERMIT NO.			FARMINGTON OF THE COMMENT OF STREET			Sec. 9, T-25-N, R-7-W NMPM 12. COUNTY OR PARISH 13. STATE	
16.			6412'GL			Rio_Arriba_NM	
Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON®		WATER SHUT-OFF FRACTURE TREATM SHOOTING OR ACID	ENT	REPAIRING WELL X ALTERING CASING ABANDONMENT®	
REPAIR WELL		CHANGE PLANS		(Other)			
(Other) 17. DESCRIBE P	ROPOSED OR COA	PLETED OPE	RATIONS (Clearly state all pe	Completion o	or Recomplet	f multiple completion on Well lon Report and Log form.) ucluding estimated date of starting any	
nent to t	his work.) *		and give bushing	e wastons and measured and t	true vertical	depuns for all markers and gones perti-	
7-2-84	and pa	icker.	set sand plu	gged up. Tripped ng across perfora sing failure. I	ations	of hole with tubing . Tripped in hole failed.	
7 - 3 - 84	Trippe	Tripped in hole with packer. Packer failed. Tripped out of hole.					
7-5-84	Isolated casing failure from 133' to 165'. Established circulati to surface. Squeeze cemented with 71 cu.ft. Established circula to surface. WOC.						
7 - 6 - 84	Drilled out squeeze cement. Pressure tested casing to 750 psi, did not hold. Squeeze cemented with 41 cu.ft. WOC.						
· 7-7-84	Drilled out squeeze cement. Pressure tested casing to 650 psi, held ok. Cleaned out to TD with gas. Ran 68 jts. 1 1/4" 2.33# tubing set at 2250'. Seating nipple at 2216'. Baker production packer at 2148'. Loaded tubing - casing annulus with correspondinhibitor. JUL3 0 1984						
18. I hereby ce	ertify that the	oregoing is	true and correct	0	IL CO		
SIGNED_	Signi	Dra	field title		lerk DIS	J. DATE July 25, 1984	
(This space	e for Federal o	State offic	e use)		ACCE	PTED FOR KEOUND	
APPROVEI	NS OF APPRO	VAL, IF A	TITLE			JUL 2: 1984	
			NA	MOCC		MINGTON RESOURCE AREA	
•			*See Instruc	ctions on Reverse Side	FARI BY 6	WINDTON RECOGNITION	