

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

Cont. #116

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Tiger

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Tapacito PC

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T26N, R3W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

N. M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Jerome P. McHugh

3. ADDRESS OF OPERATOR

Box 234, Farmington, N. M. 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1850' fsl 1450' fel

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

7192' Gr.

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/19/70 PSTD 3935'. Ran Dresser Atlas Gamma Ray Correlation log, perforate 2 jets per ft. 3646' - 56' - logging and perforating cone over mast pole.

12/20/70 PSTD 3935'. Sencoff fractured Pictured Cliffs formation 3646' - 56' with 30,000# 10-20 sand, 1105 bbis. water. Breakdown - 3400 psi. Spurthead 300 gal. 15% HCl. I.F. 2700 psi, Ave. 2500 psi. Main 2900 psi. Final 2600 psi. Instant shut in 600 psi. 15 min. shut in 500 psi. Ave. I.R. 46 B/M.

12/23/70 Move in Bedford pulling unit.

12/26/70 Installed tubing head, ran 119 jcs. 1 1/4" O.D., 2 1/2", V-55 10R 500 tubing set at 3035' R.K.B.. Sub tubing 3 hrs.

18. I hereby certify that the foregoing is true and correct

SIGNED Original signed by T. A. Dugan

TITLE Engineer

DATE 1/14/72

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side

JAN 16 1971