Form 9–331 Dec. 1973	Form Approved. ⇒ Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF 079266
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
CHANDS NOTICES AND DEPORTS ON WELLS	7. UNIT AGREEMENT NAME
SUNDRY NOTICES AND REPORTS ON WELLS	#4T.F 8 8T.A
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	
<b>4</b> -1	8. FARM OR LEASE NAME
1. oil gas K other	
2. NAME OF OPERATOR	9. WELL NO. → # 25 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Box 289, Farmington, N. M. 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA ### 설명 # 개통(###
below.)	NMPM Sec. 28, T-26-N, R-6-W
AT SURFACE: 1030'N, 990' E, Sec. 28, T26N, R6W	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	Rio Arriba New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<b>电影</b> 点
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	6669' GL
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	were the second of the second
TEST WATER SHUT-OFF	
FRACTURE TREAT	ROANDAY LAGIN - EL SIEE - L
SHOOT OR ACIDIZE	
	(NOTE: Report results of multiple completion or zone change on Form 9-330.)
MULTIPLE COMPLETE	
	2020年,6月1日 - 1987年 - 第二日 - 1987年 - 第二日
ABANDON*	Assistant of the second of the
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is different measured and true vertical depths for all markers and zones pertiner. A packer was set in the above well at 7137' isolate a casing failure. A request was apprevaluation for 90 days. Since that time, the by swabbing methods. The packer was determined and replaced on March 10, 1982. Swabbing expressions.	on January 30, 1982, to temporarily proved to produce the well for he well has not been induced to flow ined to be defective and was pulled fforts were resumed with no success.
We request a 30 day extension to unload the	well, at which time we will repair

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct Production April 15, Engineer DATE ; Ē: 13:2 APPROVED BY CONDITIONS OF APPROVALATIONS OF DATE FarJAMES F. SIMS

DISTRICT ENGINEER

30-day extension begins May 1, 1982

or plug and abandon it.