

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

5. Lease Number  
SF-078876

6. If Indian, All.or  
Tribe Name

2. Name of Operator  
Meridian Oil Inc.

7. Unit Agreement Name  
Canyon Largo Unit

3. Address & Phone No. of Operator  
Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number  
Canyon Largo Unit #114

9. API Well No.

4. Location of Well, Footage, Sec, T, R, M.  
990'N, 800'E Sec.33, T-25-N, R-7-W, NMPM

10. Field and Pool  
Ballard Pictured Cliffs

11. County and State  
Rio Arriba County, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☒ Notice of Intent

☐ Abandonment

☐ Change of Plans

☐ Subsequent Report

☐ Recompletion

☐ New Construction

☐ Final Abandonment

☐ Plugging Back

☐ Non-Routine Fracturing

☒ Casing Repair

☐ Water Shut Off

☐ Altering Casing

☐ Conversion to Injection

☐ Other

13. Describe Proposed or Completed Operations

It is proposed to repair a casing leak in the subject well per the following procedure (see attached wellbore schematic):

TOOH w/tbg & pkr. Set a RBP above the Pictured Cliffs @ 2000'. Isolate and squeeze the leak in the 2 7/8" casing w/Class "B" neat cmt. Drill out squeeze and pressure test. Pull RBP. TIH w/tbg and pkr. Return well to production.

**RECEIVED**

OCT 8 1991.

OIL CON. DIV.  
DIST. 3

14. I hereby certify that the foregoing is true and correct  
Signed *Barry B. Smith* (LS) Title Regulatory Affairs Date 9-23-91

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_  
CONDITION OF APPROVAL, IF ANY:

DATE

NMCCD

Canyon Largo Unit #114  
Unit A of Sect 33-T25N-R7W  
Rio Arriba County, New Mexico

Wellbore Schematic

CURRENT

PROPOSED

